File No.RDSO-BnS0EBS(INSP)/65/2023-O/o ED/BnS/RDSO

टेलीफोन / Tele:DOT-2465705(O) 2452426(Res.) Rly.-42122(O) 43122(Res.) फैक्स / Fax:91-0522-2465705 E-mail: dsb2rdso@gmail.com



भारत सरकार—रेल मंत्रालय
अनुसंधान अभिकल्प और मानक संगठन
कमरा नं0—223, एनेक्सी—व्बिल्डिंग,
मानकनगर, लखनऊ — 226011
Room No. 221, Annexi-II Building,
Research Design & Standards Organisation
(Government of India-Ministry of Railways)
Manak Nagar, Lucknow- 226011.

Date: 28.07.2023

No: CBS/HSFG/Reg/Stalwart

M/s. Stalwart Technosource India Private Limited 401 A, 4th floor Royale avenue Dr. Vegas Street, Kalbadevi, Marine lines(East) Mumbai-400002

Sub: Continuation in the approved list of RDSO for fabrication of HSFG bolting assemblies with direct tension indicator washer with work address at Plot No. D 57/1 Addi. Ambernath Anand Nagar, MIDC, Ambernath East, Thane-421506 Mumbai, Maharashtra.

- 1. (a) Based on Quality Audit of the infrastructure, T&P and other facilities installed at work address M/s. Vidushi Wire Pvt. Ltd., Plot No. D 57/1 Addi. Ambernath Anand Nagar, MIDC, Ambernath East, Thane-421506 Mumbai, Maharashtra, your firm registration is hereby continued in the approved list of RDSO for fabrication of HSFG bolting assemblies with direct tension indicator washer.
- (b) Based on request and decleration by M/s. Vidhusi Wire Pvt. Ltd. competant authority has approved the office address of firm as M/s. Stalwart Technosource India Private Limited: 401 A, 4th floor Royale Avenue, Dr. Vegas Street, Kalbadevi, Marine lines (East) Mumbai-400002.
- 2. Any change in the address of your office or manufacturing units shall be brought to the notice of Director General/B&S, RDSO, Lucknow. Firm will be liable to be dropped from the approved list if your product is found unsatisfactory at any stage of fabrication and inspection or on any other violation as mentioned in ISO documents.
- 3. This continuation in the approved list of RDSO will be valid for a period up to **31.10.2029**. Next quality audit shall be initiated as per RDSO ISO document No. QO-D-8.1-13.
- 4. The further continuation in the approved list of RDSO will be subject to Quality Audit which generally will be initiated after three years from the previous quality audit. However, if special condition warrants, Quality Audit may be conducted earlier also.
- 5. It is the responsibility of the firm to facilitate the RDSO Team for conducting Quality Audit as & when required.

Please acknowledge receipt of the letter.

Digitally Signed by Pradeep Kumar (Pradeep Kumar) 1:16:32 Diesem//parsynd For Director General/B&S

Copy forwarded for information and necessary action to:

- Chief Bridge Engineer:
 - 1. Central Railway, Mumbai CST-400 001.
 - Eastern Railway, Fairlie Place, Kolkata-700 001.
 - 3. East Central Railway, Hazipur-844 101
 - 4. East-Coast Railway, Bhubaneshwar-751 016.
 - 5. Northern Railway, Baroda House, New Delhi-110001.
 - 6. North-Central Railway, Allahabad-211 001.